

MATERIAL SAFETY DATA SHEET

PRODUCT NAME: PLASTER OF PARIS
PRODUCT CODE: 8022

HMIS CODES: H F R P
0 0 0

SECTION I - MANUFACTURER IDENTIFICATION

MANUFACTURER'S NAME: Custom Building Products, Inc.
ADDRESS: 6511 SALT LAKE AVE., BELL, CA. 90201
EMERGENCY PHONE: (323) 582-0846 INFORMATION PHONE: (323) 582-0846
DATE REVISED : 04-14-03 NAME OF PREPARER : STEVE TAYLOR

SECTION II - INGREDIENTS/SARA III INFORMATION

COMPONENTS	CAS NUMBER	OSHA PEL	OCCUPATIONAL EXPOSURE	VAPOR PRESSURE mm Hg @ TEMP	Wt. %
			LIMITS ACGIH TLV		
GYPSUM	7778-18-9	15mg/m3	10mg/m3		80-100

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING RANGE: N/A SPECIFIC GRAVITY (H2O=1): 2.7
VAPOR DENSITY: HEAVIER THAN AIR EVAPORATION RATE: SLOWER THAN ETHER
SOLUBILITY IN WATER: SLIGHT
APPEARANCE AND ODOR: WHITE POWDER; NO ODOR

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT: N/A
FLAMMABLE LIMITS IN AIR BY VOLUME - LOWER: N/A UPPER: N/A

EXTINGUISHING MEDIA: NONE KNOWN

SPECIAL FIREFIGHTING PROCEDURES
NONE

UNUSUAL FIRE AND EXPLOSION HAZARDS
NONE

===== SECTION V - REACTIVITY DATA =====

STABILITY: STABLE

CONDITIONS TO AVOID
NONE

INCOMPATIBILITY (MATERIALS TO AVOID)
POSSIBLE REACTIVITY WITH STRONG MINERAL ACIDS.

HAZARDOUS DECOMPOSITION OR BYPRODUCTS
REACTION WITH ACIDS WILL EVOLVE CARBON DIOXIDE.
HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

===== SECTION VI - HEALTH HAZARD DATA =====

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE
REMOVE TO FRESH AIR.

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE
MAY DEVELOP SUFFICIENT HEAT TO CAUSE BURNS TO SKIN IF A LARGE MASS IS KEPT
IN CONTACT WITH SKIN WHILE HARDENING. PARTICLES MAY CAUSE IRRITATION TO EYES.

SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE
NONE

INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE
PLASTER HARDENS WHEN WETTED AND IF INGESTED MAY RESULT IN OBSTRUCTION.
SEE PHYSICIAN.

HEALTH HAZARDS (ACUTE AND CHRONIC)
ACUTE: NONE
CHRONIC: NONE

CARCINOGENICITY: NTP? NO IARC MONOGRAPHS? NO OSHA REGULATED? NO NONE

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE
NONE

EMERGENCY AND FIRST AID PROCEDURES
EYE CONTACT: FLUSH WITH WATER TO REMOVE PARTICLES. IF IRRITATION PERSISTS,
SEE PHYSICIAN.
SKIN CONTACT: WASH WITH SOAP AND WATER.
INHALED: REMOVE TO FRESH AIR.

SWALLOWED: IF INGESTED, SEE PHYSICIAN BECAUSE OF POSSIBLE BLOCKAGE.

===== SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE =====

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED
CLEAN UP USING DRY METHODS THAT DO NOT DISPERSE DUST INTO THE AIR.
AVOID BREATHING DUST. EMERGENCY PROCEDURES ARE NOT REQUIRED.

WASTE DISPOSAL METHOD
CAN BE TREATED AS COMMON WASTE.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING
NONE

OTHER PRECAUTIONS
NONE

===== SECTION VIII - CONTROL MEASURES =====

RESPIRATORY PROTECTION
NIOSH APPROVED RESPIRATOR FOR NUISANCE DUST.

VENTILATION
LOCAL EXHAUST.

PROTECTIVE GLOVES
NONE REQUIRED.

EYE PROTECTION
DUST GOGGLES OR SAFETY GLASSES.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT
NONE REQUIRED.

WORK/HYGIENIC PRACTICES
KEEP SPILLED MATERIALS CLEANED UP.

===== SECTION IX - DISCLAIMER =====

DISCLAIMER
THE INFORMATION PRESENTED HERE IS BELIEVED TO BE ACCURATE BUT IS NOT
WARRANTED TO BE, WHETHER ORIGINATING WITH THE COMPANY OR NOT. RECIPIENTS ARE
ADVISED TO CONFIRM IN ADVANCE OF NEED, THAT THE INFORMATION IS CURRENT,
APPLICABLE, AND SUITABLE TO THEIR CIRCUMSTANCES.